

DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch
690 Walnut Ave.St. 150
Vallejo, CA 94592-1133
(707) 649-5453
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.28**WELDING INSPECTION REPORT****Resident Engineer:**Pursell, Gary**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-012551**Date Inspected:** 13-Feb-2010**Project Name:** SAS Superstructure**OSM Arrival Time:** 700**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 1900**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China**CWI Name:** Du Zhi Qun**CWI Present:** Yes No**Inspected CWI report:** Yes No N/A**Rod Oven in Use:** Yes No N/A**Electrode to specification:** Yes No N/A**Weld Procedures Followed:** Yes No N/A**Qualified Welders:** Yes No N/A**Verified Joint Fit-up:** Yes No N/A**Approved Drawings:** Yes No N/A**Approved WPS:** Yes No N/A**Delayed / Cancelled:** Yes No N/A**Bridge No:** 34-0006**Component:** Tower**Summary of Items Observed:**

On this day CALTRANS OSM Quality Assurance (QA) Inspector Shailesh Gaikwad was present during the times noted above for observations relative to the fabrication of the SAS Superstructure being performed by Zhenhua Port Machinery Company (ZPMC) at Changxing Island in Shanghai, China. QA observed and/or found the following:

BAY 10

This QA Inspector performed Random Visual Testing (VT) of the area previously tested and accepted by ZPMC Quality Control personnel. The member is identified as North Tower lift 2 Skin D location (Cable tray supports). The weld designations reviewed are as follows.

Z69-0-B/F-22-1-N,

Z69-0-B/F-22-1-N,

NDT Notification No-005207

This QA Inspector observed the following work in progress:

BAY 10

Repair Welding:

This QA Inspector observed ZPMC qualified welding personnel identified as 057258, Perform Shielded Metal Arc Welding (SMAW) on Tower Strut. The weld identified as ND1-STSA3-1-89M-1-26A/B. ZPMC QC Identified as Jiang La Mei, with Critical welding repair report, CWR-T-CWR566, The welding parameters as measured using QC's calibrated instrument appeared to be in general compliance with WPS-485-SMAW-2G (2F) - Repair. For

WELDING INSPECTION REPORT

(Continued Page 2 of 3)

more information see attached photos.

This QA Inspector observed ZPMC qualified welding personnel identified as 066733, Perform Flux Core Arc Welding (FCAW) on South tower lift 4 Fit Lug. The weld identified as SSSL4-1C/L-98, near double diaphragm 119M top. ZPMC CWI Identified as Gang liang Zhu, The welding parameters as measured using QC's calibrated instrument appeared to be in general compliance with WPS-B-T-4333-Tc-P4-F. For more information see attached photo.

This QA Inspector observed ZPMC qualified welding personnel identified as 066733, Perform Flux Core Arc Welding (FCAW) on South tower lift 4 Fit lug. The weld identified as SSSL4-1F/L-30, near double diaphragm 123M bottom. ZPMC CWI Identified as Gang liang Zhu, The welding parameters as measured using QC's calibrated instrument appeared to be in general compliance with WPS-B-T-4333-Tc-P4-F.

BAY 11:

This QA Inspector observed ZPMC qualified welding personnel identified as 042195. Perform Submerged Arc Welding (SAW) on Angle connection Plate. Joint identified ED1-SA4-68-127M-1-1B, ED1-SA4-68-127M-2-1B, ND1-SA4-68-123M-6-1B, ZPMC QC Identified as Mao Bin Bin. The welding parameters as measured using QC's calibrated instrument appeared to be in general compliance with WPS-B-T-3221-Tc-U5-S-1.

Unless otherwise noted, all work observed on this date appeared to be in general compliance with the applicable contract documents.



Summary of Conversations:

Only general conversation was held between QA and QC concerning this project.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Skyler Guest phone: 15000422360, who represents the Office of Structural

WELDING INSPECTION REPORT

(Continued Page 3 of 3)

Materials for your project.

Inspected By: Gaikwad,Shailesh

Quality Assurance Inspector

Reviewed By: Clifford,William

QA Reviewer